Incoming Mo53005

From:

"Jensen, Doug (KUCC)" <jensend@kennecott.com>

To:

"Penny Berry" <pennyberry@utah.gov>

Date:

4/22/2008 6:28:26 AM

Subject:

FW: 042108report

Penny,

Please file this under M/053/005

Thanks

Doug

From: Dan and Lorene [mailto:danandlorene@skyviewmail.com]

Sent: Monday, April 21, 2008 6:32 PM

To: Jensen, Doug (KUCC) Cc: dslyter@infowest.com Subject: 042108report

Report

Dan Slyter

522 N. 700 East

Washington, Utah- 84780 Date: April 21, 2008

State Contract # 986739 Goldstrike Reclamation and Monitoring

Correspondence with BLM and DWR

Doug, I went out to the mine site on Friday, April 18th. The rain gauge at Guzzler # 2 was empty. We have had no rain for 30 days and the

snow was almost gone on the backside of Squaretop Mountain. I picked up plastic tubing and sheeting. I concentrated down the slope of Quail dam. I shoveled out the distribution box and worked on valve # 3 until I had it working and open again. The heap off flow had increased to 5.5 GPM.

I didn't see any sign of Chukers but I did see about 40 turkeys down in upper Arsenic gulch.

The East Fork was running about 4.0 CFS. I assume it was snow melt that is causing the East Fork to run so high. The heaps had not greened up much do to cold nights. It appears we won't have as much Cheat Grass as last year. The clover and alfalfa was starting to grow.

The road was still in very good shape. I had a large pile of HDPE culvert connectors, fencing and liner material I collected from the Quail Dam area.

That's all for this month-

Dan Slyter